



ASSEMBLY INSTRUCTION





MELFORT EXTENSION






ROWICO

HOME




<p>1 x1</p> 	<p>Ax6</p>  <p>M8x50</p>
<p>2 x2</p> 	<p>Bx6</p>  <p>Ø8/Ø16</p>


Note:
Improper use, improper assembly and mishandling may lead to defects/ cracks appearing.



4



5



Storage

